ZHEJIANG DEJIA NEW MATERIAL CO.,LTD.
1.LUHONG ROAD,QIANJIANG INDUSTRIAL ZONE, HAINING CITY ZHEJIANG,CHINA

The following sample(s) was/were submitted and identified on behalf of the client as:

| | | |
|---|---|---|
| Sample Description | : | (A)PP FABRIC |
| Sample Color | : | (A)Blue |
| End Use | : | (A)Cover |
| Sample Receiving Date | : | Aug 12, 2025 |
| Testing Period | : | Aug 12, 2025 - Aug 21, 2025 |
| Test Result(s) | : | Unless otherwise stated the results shown in this test report refer only to the sample(s) tested, for further details, please refer to the following page(s). |
| Test Performed | : | Selected test(s) as requested by applicant |

| **Conclusion** | **A** | **Remark** |
|---|---|---|
| Determination Of Resistance to Damage By Flexing | See Results | |

Signed for and on behalf of
SGS-CSTC Standards Technical Services Co., Ltd. Hangzhou Branch

jack-yl_zhang(Account Executive)

SGS-CSTC Standards Technical Services Co., Ltd. Hangzhou Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

1/F., Building 6 & 3-6/F., Building 4, No.1180, Bin'an Road, Changhe Street, Binjiang District, Hangzhou, Zhejiang, China 310052 t (86-571) 86791199 www.sgsgroup.com.cn
中国・浙江・杭州市滨江区长河街道滨安路1180号4幢3-6层、6幢1层 邮编: 310052 t (86-571) 86791199 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

Test Result

**Determination Of Resistance to Damage By Flexing^**

(AS 4878.9-2001, Method A)

After 400000 cycles

| - | Unit | A | Requirement |
|---|---|---|---|
| Extent of Damage | - | 0 | - |
| Description of Damage | - | No change | - |
| Depth of Cracking | - | NIL | - |
| Number of Cracks | - | 0 | - |
| Length of Cracks | mm | 0 | - |
| Delamination in Appearance | - | None | - |

Remark:
Grading for Extent of damage:
0-None
1-Slight
2-Moderate
3-Severe

Grading for Depth of crack:
Nil -No cracking
A-Surface or finish crack, not exposing the cellular of middle layer
B-Cracking into but not right through the middle layer. Or, in the case of single-layer coating, not exposing the base fabric
C-Cracking through to the base fabrid
D-Cracking right through the material

For Number of cracks section:
Over 10 -More than 10 crack observed

**^This test was carried out by SGS Shanghai Laboratory**

SGS-CSTC Standards Technical Services Co., Ltd. Hangzhou Branch Commercial Laboratory.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
1/F., Building 6 & 3-6/F., Building 4, No.1180, Bin'an Road, Changhe Street, Binjiang District, Hangzhou, Zhejiang, China 310052 t (86-571) 86791199 www.sgsgroup.com.cn
中国・浙江・杭州市滨江区长河街道滨安路1180号4幢3-6层、6幢1层 邮编: 310052 t (86-571) 86791199 sgs.china@sgs.com
Member of the SGS Group (SGS SA)

**Sample Photo**



Unless otherwise stated, the decision rule for conformity reporting is based on Binary Statement for Simple Acceptance Rule (w=0) stated in ILAC-G8:09/2019.

***End of Report***

Scan to see the report

SL625063390424O1TX

Verification:
check.sgsonline.com.cn

SGS-CSTC Standards Technical Services Co., Ltd. Hangzhou Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

1/F., Building 6 & 3-6/F., Building 4, No.1180, Bin'an Road, Changhe Street, Binjiang District, Hangzhou, Zhejiang, China 310052 t (86-571) 86791199 www.sgsgroup.com.cn
中国・浙江・杭州市滨江区长河街道滨安路1180号4幢3-6层、6幢1层 邮编: 310052 t (86-571) 86791199 sgs.china@sgs.com

Member of the SGS Group (SGS SA)